

Federal

CONNECTICUT LOCAL BRIDGE PROGRAM

Fiscal Year 2005

PRELIMINARY APPLICATION

BEAR HILL ROAD over

NATCHAUG RIVER


Chaplin, CT

ConnDOT Bridge No. 04601

Prepared for the
Connecticut Department of Transportation
Local Bridge Program
Newington, Connecticut

Prepared by
WMC Consulting Engineers
87 Holmes Road
Newington, Connecticut

April 2004



CONNECTICUT DEPARTMENT OF TRANSPORTATION

James F. Byrnes, Jr., Commissioner



PRELIMINARY APPLICATION FOR THE LOCAL BRIDGE PROGRAM

Preliminary application is hereby made by the Town/City/Borough of **Chaplin** for possible inclusion in the Local Bridge Program for **Fiscal Year 2005** for the following structure:

North Bear Hill Road over Natchaug River.

Bridge Location: **.4 miles from Route 198**

Bridge Number: **04601**

Length of Span: **75 feet**

Sufficiency Rating: **56.77**

Priority Rating: **54.07**

Evaluation & Rating Performed by: X State Forces Others

If Others, Name of Professional Engineer: _____

Connecticut Professional Engineers License Number: _____

Engineering Firm: _____

Engineer's Address: _____

Description of Existing Condition of Structure: *(attach description)*

Description of Project Scope: *(note repair code; attach narrative/preliminary plans & specifications).*

Name of Municipal Official to Contact: **Rusty Lanzit**

Mailing Address: **Town Hall, Rte. 198, 495 Phoenixville Rd., P.O. Box 286,
Willimantic, CT 06235-0286**

Telephone: **(860) 455-9455**

FAX: **(860) 455-0027**

E-mail: _____

Preliminary Cost Figures:

Preliminary Engineering Fees (Include Breakdown of Fees) <i>(Not to Exceed 15% of Construction Costs)</i>	\$ <u>162,000</u>
Rights-of-Way Cost (If Applicable)	\$ <u>N/A</u>
Municipally Owned Utility Relocation Cost	\$ <u>N/A</u>
Estimated Construction Costs (Include Detailed Estimate)	\$ <u>1,080,000</u>
Construction Engineering (Inspection, Materials Testing) <i>(Not to Exceed 15% of Construction Cost)</i>	\$ <u>162,000</u>
Contingencies <i>(10% of Construction Costs Only)</i>	\$ <u>108,000</u>
Total Estimated Project Cost	\$ <u>1,512,000</u>

Financial Aid Data:

Federal Reimbursement: *(Limited to qualifying bridges – See Appendix 1)*

Total Estimated Project Cost multiplied by 80%:

Project Reimbursement Request \$ \$1,209,600.00

State Local Bridge Project Grant: *(Cannot be combined with Federal reimbursement)*

Allowable Grant Percentage _____ % of Total Cost.

Project Grant Request \$ _____


State Local Bridge Project Loan: *(Maximum 50% of total project cost)*

Project Loan Request \$ 0

Schedule: (Anticipated Dates)

Public Hearing Conducted:	Fall 2005
Design Completion:	Winter 2005/6
Property Acquisition Completion:	N/A
Utilities Coordination Completion:	N/A
Construction Advertising:	Winter 2005/6
Supplemental Application Submission:	Spring 2006
Start of Construction:	Spring 2006
Completion of Construction:	Fall 2006

I hereby certify that the above is accurate and true, to the best of my knowledge and belief.

Signature: 
(Chief Elected Official, Town Manager, or other Officer Duly Authorized)

Date: 5/13/04

Return completed applications to: Mr. Stanley C. Juber
Administrator of the Local Bridge Program
Connecticut Department of Transportation
2800 Berlin Turnpike, P.O. Box 317546
Newington, Connecticut 06131-7546

2. Description / Existing Condition

The bridge carrying Bear Hill Road over the Natchaug River consists of corrugated metal bridge deck on two simple span multiple plate steel girders with a bituminous concrete wearing surface. The original structure was built in 1969 and was rehabilitated in 1990. The existing bridge travel way width is approximately 23.4 feet and is referenced as ConnDOT Bridge No. 04601. The bridge currently has a posted weight limit of 30 tons. The structure has a maximum span of 36 feet and is eligible for State and Federal funding under the Local Bridge Program for the fiscal year 2005.

Deck

According to the ConnDOT bridge inspection report, dated July 9, 2003 the deck is in fair condition (rating=5). The corrugated metal decking is surfaced with ½ inch oil/stone wearing surface over 2 inches of bituminous concrete. There are open cracks in the surface at the deck ends and in the pier area both in the original surface and bituminous patches. The undersides of the corrugated metal decking show light rusting at the fascias and along the form edges. The overlapping forms at the pier show light to heavy rusting with active leakage. The bridge rail consists of H-beam uprights welded to the fascia beams with an angle iron cap and metal beam rail.

Superstructure

According to the ConnDOT bridge inspection report, dated July 9, 2003, the superstructure is in poor condition (rating=4). There are no bearings over the westerly abutment with the steel stringers resting directly on the bridge seat. The easterly abutment bearings are thin plate about 1/8" thick with moderate rust and thin laminar rust between the plates and steel stringer lower flanges. Bearing #8 is undermined due to spalling of the bridge seat. The pier bearing appear to made of plow blade material. The pier cap is uneven and bearing surface with the stringers is not uniform.

The steel stringers are salvage material. Many of the stringers show flame cut holes on the ends. All stringer ends of the easterly span show heavy laminar rusting of the web and both top and bottom flanges with section loss. Stringers #5 & #6 of the westerly span also show heavy laminar rusting over the pier with section loss. Stringer #5 has a perforation hole in the lower web area measuring 23" long by up to 1" high.

Substructure

According to the ConnDOT bridge inspection report, dated July 9, 2003, the substructure is in poor condition (rating=4). The cast in place concrete abutments were rehabilitated in 1990, they have a stepped block shape with a concrete rub coat. Both abutments show vertical cracking and delamination of the rub coat. The easterly cap shows spalling at the edges. The back walls are of channel steel with areas of heavy rusting and some laminar sheets. The pier cap was not rehabilitated and shows areas of spalling, loose and punky concrete. A square block structure

has been cast around the original pier stem, it shows random cracking and areas of light honeycomb. The westerly abutment wing walls are constructed of precast concrete blocks. There are boulders placed along the northern side of the easterly abutment, there is no wingwall at the southerly end of the abutment.

Channel and Channel Protection

According to the ConnDOT bridge inspection report, dated November 9, 1990, the channel is in satisfactory condition (rating=6). There is 2 vertical feet of scour along the nose of the pier. There is embankment encroachment with banks overhanging the channel, there is no riprap armoring.

Approach Condition

According to the ConnDOT bridge inspection report, July 9, 2003, the approach is in satisfactory condition (rating=6). The metal beam rail on the structure is carried onto the approaches. The connection at the northeasterly corner is partially disconnected. The pavement at the ends of the bridge have been patched numerous times and is breaking up.

3. Proposed Condition Replace Entire Structure

The existing structural evaluation rating is 4 (meets minimum tolerable limits). Based on the structural condition, the bridge warrants a complete replacement. The proposed replacement would include the following:

- 1) Remove the existing structure in its entirety, including removing the existing to below streambed grade.
- 2) Install new reinforced concrete abutments and wingwalls founded on steel piles.
- 3) Install a new prestressed concrete deck with a 26' travelway.
- 4) Install a new bridge rail system on new reinforced concrete parapets.
- 5) Place membrane waterproofing over the entire structure.
- 6) Install new guide railing and approaches.

Estimated construction cost for the work is \$1,080,389.00. A detailed estimate is provided on the following pages.

Structure No.	04601	Town	CHAPLIN
Inspection Date	7/9/2003	Inspectors	TEAM 2

TABLE OF CONTENTS

Loose Forms (not bound in report)

	Number of Sheets Enclosed
Maintenance Memo	0
Flagging Memos	0
PONTIS Element Data Collection Form	1
Plan Sheets	0
Already on file <input type="checkbox"/>	

Bound Report Pages

Title Cover Sheet	1
Table of Contents	1
Executive Summary	0
Field Notes	11
Calculations:	
Load Rating Evaluation	0
Quantities & Cost Estimate	0
Photo Sheets	6
Photo Images	12

Forms

BRI-18, Bridge Inspection Form	6
BRI-19, Highway Bridge Inventory Form	2

Comments:

2/29

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: **04601**

INSPECTION DATE: **7/9/2003**

INSPECTION TYPE:	Routine	PREVIOUS INSPECTION DATE:	8/29/2001	SNOOPER REQUIRED:	No
INSPECTION PERFORMED BY:	TEAM 2	SNOOPER USED:	No		
TOWN:	CHAPLIN	FEATURE CARRIED:	NO BEAR HILL ROAD	YEAR BUILT:	1969
LOCATION:	.4 MI FROM JCT ROUTE 198	FEATURE INTERSECTED:	NATCHAUG RIVER	YEAR REBUILT:	1990
MAIN MATERIAL:	Steel	MAIN DESIGN:	Stringer/Multi-beam or Girde		

INSPECTION VISITS:	INSPECTORS:
Inspection Date: 7/9/2003	Inspector: J. Brndiar
Temperature: 72 °F	Task: LEAD BRIDGE INSPECTOR
Start Time: 7:45 AM	Inspector: P. Venoutsos
End Time: 10:00 AM	Task: BRIDGE INSPECTOR

58. DECK OVERALL RATING **5**

RATING		
OVERLAY	6	THE ONE-HALF INCH THICK, OIL AND STONE SURFACE TREATMENT, OVER TWO INCHES OF BITUMINOUS MATERIALS, OVER STAY IN PLACE FORMS, STILL SHOWS FULL WIDTH TRANSVERSE CRACKING, OPEN A MAXIMUM OF ONE INCH, MAINLY IN THE AREAS OF THE DECK, ADJACENT TO THE PIER. AREAS OF BITUMINOUS PATCHES, ARE NOTED ALONG EACH DECK END, FROM THE REPAIR OF PAST REPORTED DECK END SPALLING. BOTH DECK ENDS SHOW MULTIPLE TRANSVERSE CRACKING, WITHIN THE PAST SURFACES, AS WELL AS IN THE NEWER BITUMINOUS PATCHES. SOME SCRAPES, AND GOUGES, ALONG THE DECK ENDS ARE ALSO NOTED. BOTH SHOULDERS SHOW LIGHT TO MODERATE SAND ACCUMULATION, WITH LIGHT SURFACE GOUGES. THE OUTSIDE FASCIA DECK EDGE PLATES STILL SHOW LIGHT TO MODERATE RUSTING, ALONG THEIR EDGES.
DECK STR. CONDITION	5	THE UNDERSIDES OF THE STAY IN PLACE FORMS SHOW LIGHT RUSTING OF THE FORM EDGES, ALONG BOTH OUTSIDE FASCIAS. THE FORM OVERLAP JOINTS OVER, AND ADJACENT TO, THE PIER SHOW SIGNS OF ACTIVE LEAKAGE, AND LIGHT TO HEAVY RUSTING. AREAS OF LIGHT RUSTING ARE ALSO NOTED ALONG LOCATIONS, ADJACENT TO THE STRINGER UPPER FLANGES. THE TOTAL AREA OF DETERIORATION, IS ABOUT TWO PERCENT.
CURBS	N	THIS STRUCTURE SHOWS NO CURBS.
MEDIAN	N	THIS STRUCTURE SHOWS NO BRIDGE MEDIAN.
SIDEWALKS	N	THIS STRUCTURE SHOWS NO SIDEWALKS.
PARAPET	N	THIS STRUCTURE SHOWS NO PARAPETS, OR RAILBASES.
RAILING	7	BOTH BRIDGE RAILS ARE COMPOSED OF H-BEAM POSTS, ATTACHED TO STEEL STAND-OFFS, WHICH ARE WELDED TO THE FASCIA STRINGER WEBS, AN ANGLE IRON CAP, WITH ONE COURSE OF METAL BEAM RAIL CARRIED ACROSS THE STRUCTURE, FROM THE APPROACH ROADWAY. THE SURFACES STILL SHOW AREAS OF BLUSH, AND LIGHT SPOTTY RUSTING, WITH SMALL POCKETS OF PEELING PAINT. THERE IS STILL A MINOR COLLISION RUB ALONG THE NORTHEASTERLY CORNER.
PAINT	N	
FENCE	N	THIS STRUCTURE SHOWS NO BRIDGE FENCE.
DRAINS	N	THIS STRUCTURE SHOWS NO BRIDGE SCUPPERS, OR PVC DECK WEEPS.
LIGHTING STANDARD	N	THIS STRUCTURE SHOWS NO BRIDGE LIGHTING.
UTILITIES TYPE/SIZE	N	THIS STRUCTURE SHOWS NO UTILITIES.
CONSTRUCTION JOINTS	N	
EXPANSION JOINTS	N	WHILE THERE ARE NO FORMAL EXPANSION JOINTS, THE OVERLAY SURFACE, AND OLDER PAST REPAIRED AREAS, SHOWS MULTIPLE TRANSVERSE CRACKS, ALONG

5/30

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: **04601**

INSPECTION DATE:

7/9/2003

8. DECK

OVERALL RATING

5

EACH END OF THE STRUCTURE.

59. SUPERSTRUCTURE

OVERALL RATING

4

BEARING DEVICES **RATING** **4**

THERE ARE NO BEARINGS OVER THE WESTERLY ABUTMENT. THE STRINGERS REST ON A THIN CONCRETE LEVELING CAP. THE CAP STILL RINGS HOLLOW ALONG THE OUTSIDE OF STRINGER 9. THE BEARINGS OVER THE PIER, ARE PLOW BLADE TYPE MATERIAL. THEY SHOW A VERY WAVY TEXTURE, AND A NON-UNIFORM BEARING TO THE CAP, BECAUSE THE CAP ITSELF, IS WAVY. THEY ALSO SHOW AREAS OF HEAVY RUSTING, WITH THICK LAMINAR SHEETS, MODERATE PITTING, AND VISIBLE LOSS AREAS. THE BEARINGS OVER THE EASTERLY ABUTMENT, ARE A VERY THIN PLATE TYPE, ABOUT AN EIGHTH OF AN INCH IN THICKNESS. THEY SHOW MODERATE RUSTING, WITH THIN SHEETS OF LAMINAR, AND IMPACTED RUST BETWEEN THE PLATE, AND STRINGER LOWER FLANGES. BEARINGS FIVE, EIGHT, AND NINE, SHOW A NON UNIFORM BEARING SURFACE, AND SPREADING BETWEEN THE PLATE, AND LOWER FLANGES. BEARING THREE, SHOWS A QUARTER INCH GAP BETWEEN THE PLATE AND CAP, AND THE PLATE TO LOWER FLANGE. THE EAST EDGE OF BEARING PLATE EIGHT, EAST SPAN OVER THE PIER, IS NOW UNDERMINED UP TO 3 INCHES, DUE TO SPALLING OF THE PIER CAP.

STRINGERS **5**

THE SALVAGED STRINGER SUPERSTRUCTURE, SHOWS FLAME CUT HOLES OF VARIOUS STRINGER ENDS, OVER THE EAST ABUTMENT, AND ALONG THE FASCIA STRINGER ENDS, OVER EACH SIDE, OF THE PIER. THIS HAS BEEN PAST DOCUMENTED. THE STRINGERS SHOW AREAS OF BLUSH, AND SPOTTY RUST, TO THE WEBS AND LOWER FLANGES, OF THE INTERIOR STRINGERS. ALSO NOTED ARE MILL SCALE, FINS, AND SLIVERS. THE FASCIA STRINGERS, SHOW LIGHT TO MODERATE RUSTING OF THE INTERIOR TOP FLANGES, THRU-OUT. THE INTERIOR STRINGER TOP FLANGES, SHOW ISOLATED AREAS OF MODERATE TO HEAVY RUST AREAS. MANY BOTTOM FLANGES ARE BENT UPWARDS, AS WELL AS Laterally. STRINGER 5, OVER THE EAST ABUTMENT, SHOWS HEAVY RUSTING WITH LAMINAR SHEETS. STRINGER 7, OVER THE EAST ABUTMENT, SHOWS HEAVY RUSTING WITH LAMINAR SHEETS. STRINGER 8 OVER THE EAST ABUTMENT, SHOWS HEAVY RUSTING WITH LAMINAR SHEETS, TO THE BOTTOM FLANGE, THE EDGE HAS BEEN REDUCED. REFER TO THE SECTION LOSS NOTES. THE FLANGE HAS PAST BENT WHEN STRUCK WITH A HAMMER. STRINGER 9, OVER THE EAST ABUTMENT, THE OUTSIDE LOWER FLANGE, AND A PORTION OF THE WEB, ARE COVERED WITH SAND DEBRIS. THERE IS A BAND OF LAMINAR RUST TO THE LOWER WEB, MEASURING TWO INCHES HIGH, BY FIVE FEET IN LENGTH. THERE IS SOME PITTING. ALL STRINGERS ENDS OF THE EASTERLY SPAN, OVER THE PIER, SHOW HEAVY RUSTING WITH LAMINAR SHEETS, OF THE UPPER, AND LOWER FLANGES, AS WELL AS WEB AREAS. THERE IS LOSS OF SECTION. THE TOP FLANGES OF STRINGERS 5, AND 6, OVER THE PIER, OF THE WESTERLY SPAN SHOW HEAVY RUSTING WITH LAMINAR SHEETS, OF THE TOP FLANGES. STRINGER 5 OF THE WESTERLY SPAN, OVER THE PIER, STILL SHOWS A PERF HOLE TO THE LOWER WEB AREA, MEASURING 23 INCHES LONG, BY UP TO 1 INCH HIGH.

GIRDERS **N**

FLOOR BEAMS **N**

TRUSSES-GENERAL **N**

TRUSSES-PORTALS **N**

TRUSSES-BRACING **N**

PAINT **5**

REFER TO THE ABOVE DESCRIPTIONS.

RUST **4**

REFER TO THE ABOVE DESCRIPTIONS.

MACHINERY MOV SPAN **N**

6/20

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: 04601

INSPECTION DATE:

7/9/2003

59. SUPERSTRUCTURE

OVERALL RATING 4

RIVETS & BOLTS	N	
WELDS & CRACKS	8	THE STRINGERS ARE CHECKED HANDS-ON.
TIMBER DECAY	N	
CONCRETE CRACKING	N	
COLLISION DAMAGE	8	THE SUPERSTRUCTURE SHOWS NO COLLISION DAMAGE.
MEMBER ALIGNMENT	8	
DEFLECT. UNDER LOAD	N	
VIBR. UNDER LOAD	N	
STAND PIPES	n	
BARREL LADDERS	N	

ARE BARREL LADDERS OSHA COMPLIANT?

60. SUBSTRUCTURE

OVERALL RATING 4

	RATING	
ABUTMENTS-STEM	6	BOTH ABUTMENTS ARE A CAST IN PLACE, TRI-STEP BLOCK SHAPE, WITH A CONCRETE RUB COAT FINISH. BOTH SHOW VERTICAL CRACKING, WITH DELAMINATIONS OF THE RUB COAT, POURLINE CRACKING, SHRINKAGE WITH CURING CRACKING, HONEYCOMBING, AND LIGHT SCALE AREAS. THE WESTERLY ABUTMENT SHOWS SEVERAL DELAMINATIONS ALONG THE UPPER CAP, ADJACENT TO THE STRINGERS. THE EASTERLY CAP EDGE SHOWS SOME MINIMAL EDGE SPALLING, BUT THE BEARINGS ARE NOT THREATENED.
ABUTMENTS-BACKWALL	5	THE CHANNEL SHAPED STEEL BACKWALLS, SHOW POCKETS OF MODERATE, TO HEAVY RUSTING, SOME WITH LAMINAR SHEETS, OF BOTH FLANGE AREAS, WITH LIGHT RUST AREAS, ALONG THE WEBS.
ABUTMENTS-FOOTINGS	6	SIX LINEAR FEET OF THE FOOTING EDGE, AND TOP FASCIA, ARE STILL VISIBLE, ALONG THE WESTERLY ABUTMENT. THE PORTION THAT IS VISIBLE SHOWS LIGHT SCALING. THERE ARE ALSO TWO, CONCRETE TRANSVERSE STRUTS, BETWEEN THE PIER, AND THE WESTERLY ABUTMENT. THEY SHOW ONLY LIGHT SCALING.
ABUT.-SETTLEMENT	8	THERE ARE NO SIGNS OF SETTLEMENT TO THE ABUTMENTS.
ABUTMENTS-WINGWALLS	7	TWO FOOT, BY FOUR FOOT, CONCRETE PRE-CAST BLOCKS, ARE USED AS WINGS ALONG THE WESTERLY ABUTMENT. THEY SHOW VEGETATION, AND EMBANKMENT OVERBURDEN. BOULDERS ARE PLACED ALONG THE NORTHERLY END, OF THE EASTERLY ABUTMENT. IT SHOWS SMALL FILLER STONE VOIDS. THERE IS NO FORMAL WINGWALL ALONG THE SOUTHERLY CORNER, OF THE EASTERLY ABUTMENT.
PIERS/BENTS-CAPS	4	THE ORIGINAL PIER CAP IS VISIBLE, AND HAS NOT RECIEVED REHABILITATION REPAIRS IN THE PAST. IT STILL SHOWS AREAS OF MULTIPLE CRACKING, AND DELAMINATIONS TO THE RUB COAT, WITH HORIZONTAL POURLINE CRACKING. THE SOUTHERLY END OF THE CAP, SHOWS ABOUT 4 SQUARE FEET OF CORNER SPALLING, ANDSPALLING OF THE LOWER CAP BETWEEN THE CORNERS, ABOUT THREE INCHES IN DEPTH, REVEALING VERY LOOSE, AND PUNKY CONCRETE. THE REMAINING SURFACES WHERE NOT SPALLED, RING HOLLOW WHEN STRUCK WITH A HAMMER. THE EASTERLY FASCIA, UNDER STRINGERS THREE, AND FOUR, SHOW FOUR SQUARE FEET OF SPALLING, ABOUT TWO INCH IN DEPTH, AND 2.5 SQUARE FEET OF SPALLING, WITH ADJACENT DELAMINATIONS, UNDER STRINGER 8, PAST UNDERMINING THE BEARING PLATE, UP TO 3 INCHES.
PIERS/BENTS-PILE BENT	N	

7/28

Connecticut Department of Transportation
Bridge Inspection Report BRI-18

BRIDGE #: 04601

INSPECTION DATE:

7/9/2003

60. SUBSTRUCTURE

OVERALL RATING 4

PIERS/BENTS-COLUMN	7	A CAST IN PLACE, SQUARE BLOCK STRUCTURE, HAS BEEN CONSTRUCTED AROUND THE ORIGINAL STEM AREA, IN AN ATTEMPT TO ENCASE THE ORIGINAL STEM AREA. IT SHOWS RANDOM CRACKING, WITH AREAS OF LIGHT HONEYCOMB.
PIERS/BENTS-FOOTINGS	6	THE FOOTING IS STILL GENERALLY VISIBLE AROUND THE PERIMETER OF THE PIER. THE NORTHERLY INLET FASCIA OF THE FOOTING, IS STILL EXPOSED UP TO 24 INCHES HIGH. THE FOOTING SHOWS LIGHT TO MODERATE SCALING, WITH TRANSVERSE CRACKING, ALONG THE CAP.
PIERS/BENTS-SETTLEMENT	8	THERE ARE NO SIGNS OF SETTLEMENT TO THE PIER.
EROSION-SCOUR	6	TWO VERTICAL FEET OF SCOUR, HAS PAST OCCURED AT THE NOSE OF THE PIER. THIS TAPERS OFF AS YOU MOVE DOWNSTREAM ALONG THE STEM.
CONCRETE CRACK-SPALL	4	REFER TO ALL ABOVE DESCRIPTIONS.
STEEL CORROSION	N	
PAINT	N	
TIMBER DECAY	N	
COLLISION DAMAGE	8	THE SUBSTRUCTURE SHOWS NO COLLISION DAMAGE.
DEBRIS	7	THERE IS LIGHT SAND DEBRIS ON THE PIER, AND ABUTMENT CAPS.

61. CHANNEL PROTECTION

OVERALL RATING 6

RATING		
CHANNEL SCOUR	6	AS NOTED EARLIER, THERE IS TWO VERTICAL FEET OF PAST NOTED SCOUR, ALONG THE NOSE OF THE PIER. THE WATER DEPTH ALONG THE INLET, CAN RANGE FROM ONLY A COUPLE OF INCHES, TO AS MUSH AS 16, AT THIS TIME. THE WATER DEPTH IN FRONT OF THE PIER, IS AS MUCH AS 2.5 FEET.
EMBANKMENT EROSION	6	EMBANKMENT ENCROACHMENT, IS STILL NOTED TO THE SOUTHWESTERLY, AND SOUTHEASTERLY BANKS. THE NORTHEASTERLY, AND NORTHWESTERLY BANKS, SHOW PAST EROSION, EXPOSING TREE ROOT SYSTEMS.
DEBRIS	6	THERE IS STILL A SILT ISLAND IN PLACE, DOWNSTREAM OF THE PIER. LIGHT TIMBER DEBRIS, IS NOTED ALONG THE EMBANKMENTS.
VEGETATION	6	ALL BANKS ARE WELL VEGETATED, AND OVERHANG THE CHANNEL.
CHANNEL CHANGE	6	THE CHANNEL HAS PAST CHANGED DUE TO ENCROACHMENT, EROSION, AND SCOUR.
FENDER SYSTEM	N	
SPUR DIKES & JETTIES	N	
RIP RAP	N	RIP-RAP IS NOT USED ALONG THE BANKS OF THIS CHANNEL.

62. CULVERTS & RETAINING WALL

OVERALL RATING N

APPROACH CONDITION

OVERALL RATING 6

RATING		
APPROACH SLAB	N	
RELIEF JOINTS	N	
APPROACH GUIDE RAIL	7	LONGER SECTIONS OF METAL BEAM RAILING, ARE NOTED ALONG THE WESTERLY APPROACH SHOULDERS, AND CARRIED OVER THE STRUCTURE. THE RAIL ATTACHMENT TO THE BRIDGE AT THE NORTHWESTERLY CORNER, HAS BECOME PARTIALLY DISCONNECTED, AND IS STILL BOWING OUT SOMEWHAT, AND ALSO SHOWS SOME LONGITUDINAL TORN AREAS. VERY SHORT SECTIONS OF RAILING, ARE

8/20

Connecticut Department of Transportation
Bridge Inspection Report BRI-18

BRIDGE #: **04601**

INSPECTION DATE:

7/9/2003

APPROACH CONDITION

OVERALL RATING **6**

NOTED ALONG THE EASTERLY APPROACH SHOULDERS. THE RAILING IS STILL DENTED AT THE STRUCTURE, ALONG THE NORTHEASTERLY CORNER.

APPROACH PAVEMENT **6**

THE OIL AND STONE APPROACH ROADWAY SURFACES, SHOW LONGITUDINAL, TRANSVERSE, AND RANDOM CRACKING, SOME ARE OPEN UP TO 1/2 INCH, PAST BREAKAGE ALONG THE EASTERLY, AND WESTERLY ENDS OF THE STRUCTURE, BITUMINOUS PATCHES, MULTIPLE TRANSVERSE CRACKING WITH LIGHT BREAKAGE ALONG BOTH DECK ENDS, SETTLEMENT ALONG BOTH DECK ENDS OF UP TO 1 INCH, AND AN UNEVEN SURFACE. THERE ARE NEWER BITUMINOUS PATCHED AREAS ALONG EACH END OF THE STRUCTURE, DUE TO HOLES FOUND, IN THE PAST.

APPROACH EMBANKMENT **7**

MINOR EROSION, FROM ROADWAY RUN-OFF, IS NOTED ALONG ALL BANKS.

TRAFFIC SAFETY FEATURES:

BRIDGE RAILINGS **0**

TRANSITIONS **0**

APPROACH GUARDRAILS **0**

APPR. GUARDRAIL ENDS **0**

LOAD POSTING

SINGLE UNIT (TONS) **30**

HS (TONS)

4 AXLE (TONS)

3S2 (TONS)

ADVANCE WARNING Y/N **8**

LEGIBILITY **8**

VISIBILITY/LOCATION **8**

MISC.

MIN VERT. UNDERCLR.

0' 0"

POSTED CLR. UNDER BRIDGE

0' 0"

POSTED CLR. ON BRIDGE

0' 0"

ADVANCE WARNING (Y/N)

No

SPEED LIMIT (IF ANY)

0 MPH

CHARACTER OF TRAFFIC

THE TRAFFIC VOLUME WAS LIGHT OVER THE STRUCTURE DURING THE INSPECTION, WITH ALL TYPES OF VEHICLES NOTED.

ADDITIONAL NOTES

DURING THE 2001 INSPECTION OF THIS STRUCTURE, THE CHAPLIN TOWN CREW HAD TO BE NOTIFIED, VIA SENIOR ENGINEER DAVID TASSAVOR, DUE TO A HOLE ALONG THE EASTERLY END OF THE STRUCTURE, OVER THE BACKWALL, MEASURING ABOUT .5 SQUARE FOOT. THIS AREA WAS FILLED IN WITH BITUMINOUS PATCH. THIS HOLE APPEARED TO BE A HAZARD TO MOTORCYCLE, OR BICYCLE TRAVEL. IT APPEARS THAT THIS AREA MAY AGAIN OPEN UP SOMETIMES IN THE FUTURE.

ADDITIONAL COMMENTS:

Connecticut Department of Transportation
Bridge Inspection Report BRI-18

BRIDGE #: 04601

INSPECTION DATE:

7/9/2003

Inspectors' Signatures:

1)

John C. Brindley

Date:

07/09/2003

NICET AET

081734

EXP. 2-2005.

2)

Date:

--/--/--

3)

Date:

--/--/--

4)

Date:

--/--/--

P.E. Signature:

P.E.#:

Date:

--/--/--

Reviewed by:

J. Day

CDOT

Date:

10/10/03

BRIDGE NUMBER 04601 , THE TOWN OF CHAPLIN – NORTH BEAR
HILL ROAD OVER THE NATCHAUG RIVER.

MAINTENANCE RECOMMENDATIONS AS OF AUGUST 29, 2001 BY
LEAD BRIDGE INSPECTOR JOHN G. BRNDIAR.

- 1) SEAL THE SURFACE CRACKING OVER THE STRUCTURE.
- 2) CLEAN AND PAINT THE BRIDGE RAILINGS.
- 3) APPLY PROPER JOINTS ALONG THE ENDS OF THIS STRUCTURE.
THE BITUMINOUS SURFACE IS BREAKING UP, CRACKING, AND
PAST SPALLED. THE SURFACE WILL AGAIN BREAK UP, AND
CREATE HOLES ALONG THE ENDS OF THE STRUCTURE.
- 4) CLEAN AND PAINT THE BEARINGS, AND STRUCTURAL STEEL.
- 5) WELD NEW PLATE OVER THE WEBS WHERE LOSS IS NOTED.
- 6) REPAIR THE PIER CAP, WHERE SPALLING IS NOTED UNDER
STRINGER 8, AND THE BEARING PLATE IS UNDERMINED.

	7-2003	J. BRNDIAR
NO.	DATE	DESCRIPTION
REVISIONS		

Bridge Number **04601**

Inspected By: J. Burdick & P. Vencutso

Sufficiency Rating **72.8**
Previous Inspection Date **8/29/2001**

BS&E Received ☒ Data Entry By: Juan Guzman
Copies Made ☒ Data Entry Date: 12-17-03

STATE OF CONNECTICUT
DEPARTMENT OF TRANSPORTATION
BRIDGE SAFETY & EVALUATION
STRUCTURE EVALUATION
SHEET 1 OF 2 FORM BRI-19 REV 10/00

SHEET 3 OF 28 (INSP. REPORT)

90) Inspection Date 070903	Inspection Team 202	91) Frequ 24	Class: 01
Indepth Insp 6/9/1999	Deck Survey	Access 0	Flagman 0
CRITICAL FEATURE INSPECTIONS			
Type	Frequency	Team	Date
Fracture:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Uwater:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Special:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

RED FLAG

IDENTIFICATION

Bridge Name **CHAPLIN** Town Code **13810**

5) Inventory Route:
A) Record Type **1**
B) Signing Prefix **5** City Street
C) Level of Service **0** None of the bel

6) Feature Intersected **NATCHAUG RIVER**

7) Facility Carried: **NO BEAR HILL ROAD**
NORTH BEAR HILL RD

9) Location **4 MI FROM JCT ROUTE 198**
4 MILE EAST OF ROUTE 198

11) Milepoint **1.73 Miles**

16) Latitude **41 deg 48 min 00 sec**

17) Longitude **72 deg 7 min 6.00 sec**

98) Border Bridge:
A) State Code **0000** B) Percent Responsibility **%**

C) Border Town Name

99) Border Bridge Structure No

STRUCTURE TYPE AND MATERIAL

43) Structure Type, Main:
A) Material **3** Steel B) Design Type **2** Stringer/Multi-beam or

44) Structure Type, Approach:
A) Material **0** Other B) Design Type **0** Other

45) Number of Spans, Main Unit **2**

46) Number of Approach Spans **0**

107) Deck Structure Type **6** Corrugated Steel

108) Wearing Surface/Protective System:
A) Type of Wearing Surface **9** Other
B) Type of Membrane **0** None
C) Type of Deck Protection **0** None

AGE AND SERVICE

27) Year Built **1969** 106) Year Reconstructed **1990**

42) Type of Service:
A) On **1** Highway B) Under **5** WATERWAY

28) Number of Lanes:
A) On **2** B) Under **0**

29) Average Daily Traffic **200** Half ADT?: **No**

109) Percent Truck **7 %**

30) Year of ADT **1993**

19) Bypass, Detour Length **4 miles**

GEOMETRIC DATA

48) Length of Max Span **36 ft**

49) Structure Length **75 ft**

50) Curb or Sidewalk Widths:
A) Left **0.0 ft** B) Right **0.0 ft**

51) Brg Rdwy width, curb-curb **23.4 ft**

52) Deck Width, Out-Out **24.1 ft**

32) Approach Roadway Width **18 ft**

33) Bridge Median **0** No Median

Deck Area **1807 sqft**

34) Skew Angle **10 deg**

35) Structure Flared **0**

10) Inv. Rte. Min. Vert Clearance **99 ft 99 in**

47) Log Inv. Rte. Total Horiz Clr.: **23.4 ft**

47) RLog Inv. Rte. Total Horiz. Clr.: **ft**

53) Min Vert Clearance Over Bridge **99 ft 99 in**

54) Min Vert Under Clearance **N Ref 0 ft 0 in**

55) Min Lat Under Clearance on Right **N Ref 99.9 ft**

56) Min Lat Under Clearance on Left **0.0 ft**

BRIDGE COMMENTS

CLASSIFICATION	
112) NBIS Bridge Length	Yes
104) Highway System	0 Off System
26) Functional Class	9 Rural Local
100) Defense Highway	0 Not Defense Highway
101) Parallel Structure	N No parallel structure exists
102) Direction of Traffic	2 2-way traffic
103) Temporary Structure	
110) Designated National Network	0 Not on national network
20) Toll	3 On Free Road
21) Maintain	3 Town or Township Highway Agency
22) Owner	3 Town or Township Highway Agency
Report Class	L LOCAL
37) Historical Significance	5 Bridge is not eligible for National Register

WATERWAY	
DrainageBasinCode	3200
38) Navigation Control	0 No navigation control on waterway
39) Navigation Vert Clr.	0
40) Navigation Horiz Clr.	0
116) Vert-Lift Brg Nav Min	
111) Pier Abutment Protection	

PROPOSED IMPROVEMENTS	
75A) Type of Work Proposed	
75B) Work Done By	
76) Length of Struct. Improvement	ft
94) Bridge Improvement Cost	\$
95) Roadway Improvement Cost	\$
96) Total Project Cost	\$
97) Year of Improvement Cost Est.	
114) Future ADT	
115) Year Future ADT	
List No.	Project No.
	Advised

POSTED SIGNS & UTILITIES	
Other Posted Signs 1	0
Other Posted Signs 2	0
Actual P.L. Single Unit Truck	tons
Rec. P.L. Single Unit Truck	tons
Actual P.L. Semi-Trailer Truck	tons
Rec. P.L. Semi-Trailer Truck	tons
Rec. P.L. All Vehicles	tons
Posted Vert Clearance On Bridge	0 ft 0 in
Posted Vert Under Clearance	0 ft 0 in
Posted Speed Limit	0 mph
Utility	

BLANK

BLANK

STRUCTURE EVALUATION

SHEET 2 OF 2 FORM BRI-19 REV 10/00

SHEET 4 OF 28 (INSP. REPORT)

Inspected By:

S. B. B. & P. Venetis

Bridge Number	04601	NBIS Length	
Town Name	CHAPLIN	Yes	75
Facility Carried	NO BEAR HILL ROAD		
Feature Crossed	NATCHAUG RIVER		

LOAD RATING AND POSTING	
31) Design Load	0
63) Operating Rating Type	1
64) Operating Rating	36.0
65) Inventory Rating Type	1
66) Inventory Rating	21.0
Evaluation Code	L
Year of Evaluation	1998
70) Bridge Posting	2
41) Structure Status	P
Posted for load	

CONDITION		APPRAISALS	
58) Deck	5	67) Structure Evaluation	5
59) Superstructure	5	68) Deck Geometry	4
60) Substructure	5	69) Under Clear Vert & Horiz	N
61) Channel & Chan. Protection	6	71) Waterway Adequacy	4
62) Culverts	N	72) Approach Rdwy Alignment	6
		113) Scour Critical	3

Items 58 Thru 72 Checked By:

36) Traffic Safety Features:

- A) Bridge Railings
- B) Transitions
- C) Approach Guardrail
- D) Approach Guardrail End

0	
0	
0	
0	

OTHER FEATURES

Fence Required	No	Barrel Ladder	No
Fence Present	No	Stand Pipes	No
Fence Height	0.0 ft	Cat Walks	No
Fence Type	0	Movable Inspection System	No
Fence Material	0	Loose Concrete Checked?	No
Fence Top Type	0		

INSPECTION COMMENTS	
Proposed Next Indepth Insp Year	2009
Senior	daiglejl
Supervisor	vanallenrv

REVIEWED BY:

J. Day

Date

10-10-03